

IMPORTANT INFORMATION

LA**** AIR DRYER

Many air dryers are returned under warranty because of air leakage from the exhaust port. This leakage is usually found to be caused by debris from the compressor and pipe work being trapped on the purge valve seat preventing it from closing.

Excessive oil carry-over from a worn out compressor will also prevent the dryer from operating correctly

THIS IS NOT DUE TO AN AIR DRYER FAILURE AND THEREFORE CLAIMS WILL BE REJECTED

It should also be noted that when a replacement air dryer is fitted the pipe work and compressor should be checked for signs of debris. If not the problem will surely re-occur due to residual debris.



**Typical contamination found in returned units
and rejected as valid warranty claims**



Carbon



As new Purge Valve